

LABORATORY REPORT

BULK SAMPLE ASBESTOS EVALUATION BY POLARIZED LIGHT MICROSCOPY METHOD

Client: Ironwood Environmental				Project Location: 438 Vista Terrace			
Contact: Jeremy Bonacquisti				Project Reference: MC 3189			
Address: 8787 Burr Oak Rd.				TEM Project: 76215			
Roscoe IL 61073-				Analyzed by: Lori Boersma			
				Date Analyzed: 4/8/2025			

Sample Information			Asbestos Present	Fibrous Materials				Non-Fibrous Materials	
Client Sample ID	Lab ID	Color		Asbestos Fibers		Non-Asbestos Fibers		Filler	Comments
Description				Type	Percent	Type	Percent	Binder	
01 Ceiling Insulation	566877	White	None Detected	-	-	-	-	0-10	
						Glass:	90-100		
02 Wall Texture	566878	White	None Detected	-	-	-	-	90-100	
03 Wall Plaster	566879	Gray	None Detected	-	-	-	-	90-100	

Samples are analyzed following the procedures contained in the USEPA Method 600/R-93/116 July 1993. This report applies only to samples analyzed. This report may not be reproduced except in full and with the approval of TEM Environmental, Inc. This report may not be used by the client to claim product endorsement by NVLAP or any agency of the US government. An estimate of the laboratory uncertainty is available upon request.

SLM: Certain samples may warrant additional analysis beyond the standard USEPA Polarized Light Microscopy method. 1) Further testing using the point count method is recommend for friable samples found to contain less than 10% asbestos by PLM to confirm that the samples are in fact regulated asbestos containing materials (RACM) as defined by the USEPA NESHAP Regulation. 2) The optical resolution of a polarized light microscope limits the size of fibers that are visible. In cases where very small fibers may be present, such as in samples of floor tiles, vermiculite or certain construction adhesives, the result of the PLM analysis is not conclusive when the sample is reported as "None Detected" or "Trace". Further testing using transmission electron microscopy is recommended in those cases where samples may contain very small fibers which may be smaller than the resolution limit of a polarized light microscope. All such services are available for an additional fee.

Analytical services provided are subject to the Terms and Conditions listed on our website.



Report Approved by:




MC3189

CHAIN OF CUSTODY FORM

Client: Ironwood Environmental Inc	Date:	TAT	RUSH/WKD	<input type="checkbox"/>	24HR	<input type="checkbox"/>	48HR	<input type="checkbox"/>	72HR	<input type="checkbox"/>	4 DAYS	<input type="checkbox"/>	> 5 DAYS	<input type="checkbox"/>
Contact: Jeremy Bonacquisti		Project Name/No: 438 Vista terrace												
Address: 8787 Burr Oak Rd		Results Due by (Date & Time):												
City/State/Zip: Roscoe, IL. 61073		TEM Project #: 76215												
Phone: 815-378-6113	Fax:	NVLAP ID 101130 AIHA-PAT ID 101151 AIHA-AAR ID 101151												
Email: Ironwoodenv@aol.com														

Comments:

PO/Quote#:

Client ID No.	Description	Sample Volume	Bulk	Point	Gravim	Air-A	Air-O	Bulk	Chatf	Water	Micro	PCM	Other	Comments
1	Ceiling insulation													
2	Wall texture													
3	Wall Plaster													
4														
5														
6														
7														
8														
9														
10														
11														
12														
13														
14														
15														
16														
RELINQUISHED BY (SIGNATURE):		DATE/TIME	RECEIVED BY (SIGNATURE): 										DATE/TIME 4/2/25	
RELINQUISHED BY (SIGNATURE):		DATE/TIME	RECEIVED BY (SIGNATURE):										DATE/TIME	
LOGGED IN BY (SIGNATURE):		DATE/TIME	ANALYZED BY (SIGNATURE):										DATE/TIME	